

SECRET

25X1

25X1

This document contains

2 pages.

0-18-200519- 08

Copy 8 of 9 copies

29 February 1968

EVALUATION SUMMARYMission BX-6853

1. Processing and Titling - Field
2. Physical Condition - Good
3. Hypo Retention Rewashing required (Patch 3, HT-2 test)
4. Exposure (based on density) - Medium to slightly heavy
5. General Comments:
  - A. Mission contained 10 parts.
  - B. Parts 7 and 8 required dual printing.
  - C. Dye retention was prevalent throughout the mission. It was reprocessed to remove the excess dye.
  - D. Estimate cloud cover and/or water is 75%. Six parts were 100% clouds and/or water.
  - E. Part 6, Frame 403 contained an ultrasonic splice. The splice apparently was not taped (reinforced) at presplice.
  - F. The first and last frame of most parts show evidence of handling marks. These are attributed to inserting grids and replacing idents in house.
  - G. A few pinholes are noted intermittently throughout the mission record.

SECRET

25X1

SECRET

25X1

MISSION NO. BX-6853 EVALUATION REPORT

Evaluated By Q.C. Technicians

Camera Fwd/Aft

Evaluation Date 22 February 1968

Emulsion 3404

Film Metering Normal for system

Film Tracking Fair to good

Clock Operation Exposure Good

Counter Operation Operational

Data Chamber (image quality) Good

Apparent Resolution Normal

Apparent Granularity Normal

Density Medium

Contrast Medium

Discrepancies:

<u>Part</u>	<u>Frames</u>	<u>Comments</u>
1	53 71	Lacquer spot in format HT-2 test spot
2	77-152 151	Intermittent emulsion scratch Kink
3	153-228	Intermittent emulsion scratch
4	246	Emulsion pickoff
5		
6	397	Ultrasonic splice, emulsion scratch
7	532	HT-2 test spot
8	573	Edge static
9	608-684 674	Intermittent emulsion scratch Splice

Page 2  
SECRET

25X1